

# IMPORTANT KAWASAKI ENGINE SAFETY RECALL

## Leaking Fuel Filter

Fuel filters manufactured between October 2011 and August 2012 may be faulty and have the potential to leak from the weld seam. Leaking fuel increases the risk of fire hazard on general purpose engine applications.



Kawasaki FR and FX Series Engines are among the engine models affected and were installed on the following Cub Cadet riding mowers:

<b>AFFECTED 2012 Cub Cadet Models</b>			
LTX 1042KW	RZT 50 KW	Z-FORCE S 48	TANK LZ60 KW
LTX 1046KW	RZT 54 KW	Z-FORCE S 54	TANK M72 KW
LTX 1050 KW		Z-FORCE S 60	TANK SZ60

Stop using these mowers immediately and contact your Cub Cadet dealer to determine if your mower is affected. If affected, your Cub Cadet dealer will install a new fuel filter on your mower at no cost to you. For more information, please call your local Cub Cadet dealer, or call Cub Cadet Service at 1-888-848-6038 toll free week days between 8:00 a.m. and 5:00 p.m. EST and choose option 1 from the recorded menu.